



Recreation park Het Liesbos in Breda: *Pioneer in innovative natural solutions!*

For 18 months, the effects were monitored at the Liesbos recreation park in the Dutch province of Brabant. Several objects here had been coated directly over the contamination. Some important examples included six chalets that required annual cleaning due to the rapidly increasing organic pollution, also in the Brabant region.

After 1.5 years, we received the findings from Koen Quicken, one of the owners (a true visionary!), and these spoke volumes regarding the effects of the natural process of photocatalysis. All treated surfaces had been cleaned, and only in a few spots was a small amount of dead residue left behind where the rain had not yet been able to wash it away. This naturally underscored what we always advise: Clean it first, let it dry, and then coat! You will then be rid of it for years.

Koen had personally coated exactly half of a dirty chalet, and here too the effects were spectacular; one half had become even dirtier and the coated half had been cleaned. Without using a single drop of chemicals and without even touching the surface.

Let nature do the work... *wow!*

One of the demonstration surfaces that Koen Quicken also coated himself was a piece of a fence...

